

SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 048

Date. 01-06-2023

It is to certify that an inspection team headed by DR. PRASHANT MURPHYA

(Name of officers with designation) from P.H.C. SIDDHARTH SDR (Name of Department/ Office) inspected the Siddharth Public School, Tharauli, Naugarh, Siddharthnagar, U.P. (Name & Address of the school) on 19.05.2023 and found that the Siddharth Public School (Name of School) has safe drinking water facilities for the students and member of staff of the institution and maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/ State / U.T. Govt.

The above is valid for a period of one year.

Signature with seal:

Name

Designation

Dr. P.K. Mangt

नारायण चक्र साधकारा
पीठ स्वयंसेवक मंडल नोगढ़
धनपुर - सिद्धार्थनगर

To

Siddharth Public School

Tharauli Naugarh

Siddharthnagar, U.P.

प्रबन्धक
सिद्धार्थ पब्लिक स्कूल
धरौली-सिद्धार्थनगर

Principal
Siddharth Public School
Tharauli Road, Civil Lines
Siddharth Nagar (U.P.)

District Level Water Analysis Laboratory , U.P Jal Nigam (Rural),
Siddharth Nagar

Office of Executive Engineer, Construction division, U.P Jal Nigam, Infront of district hospital, Siddharth Nagar. Pin-272207 (Test Address only)

Test report

Sample ID: U1232709S12742779

User Information

Name: Sanjay Kumar Kanaujia Mobile: 7310091934
Email: sanjaybasti1994@gmail.com Pin Code:
Full Address: Village- Not available , Gram Panchayat- Not available, Block- Not available, District- Siddharth Nagar, State- Uttar Pradesh

Sample description

Source of Sample: PrivateTube well / Bore well / Well, location : Siddharth Public. Village: Tharauli
Gram Panchayat: Tharauli Block: Naugarh
District: Siddharth Nagar State: Uttar Pradesh
Address: Remarks:
Latitude: Longitude:

Date & time of sample collection

07.06.2023 | 11:18:00 AM

Date & time of sample received in lab


07.06.2023 | 01:30:00 PM


Date & time of sample analysed

08.06.2023 | 11:27:00 AM

Date & time of report generation

08.06.2023 | 11:27:00 AM



प्रधानाचार्य
सिद्धार्थ पब्लिक स्कूल
थरौली-सिद्धार्थनगर


Principal
Siddharth Public School
Tharauli Road, Civil Lines
Siddharth Nagar (U.P.)


TEST RESULTS


No.	Parameters tested	Unit of measurement	Requirement (acceptable limit) as per BIS 10500	Permissible limit (in absence of alternate source) as per BIS 10500	Test result value	Remarks
1	Chloride (as Cl)	mg/l	250	1000	209.790	Safe
2	Conductivity	micromhos per centimeter / microsiemens per centimeter	NA	NA	853.600	Safe
3	E.coli	MPN/100 ml	Shall not be detectable in any 100 ml sample	No Relaxation	0.000	Safe
4	Fluoride (as F)	mg/l	1	1.5	0.280	Safe
5	Free residual Chlorine	mg/l	0.2	1	0.020	Safe
6	Nitrate (as NO3)	mg/l	45	No Relaxation	18.000	Safe
7	pH	NA	6.5-8.5	No Relaxation	7.530	Safe
8	Sulphate (as SO4)	mg/l	200	400	18.000	Safe
9	TDS	mg/l	500	2000	371.100	Safe
10	Total Alkalinity (as Calcium Carbonate)	mg/l	200	600	36.000	Safe
11	Total Arsenic (As As)	mg/l	0.01	No Relaxation	0.000	Safe
12	Total coliform	CFU/ 100 ml	Shall not be detectable in any 100 ml sample	No Relaxation	0.000	Safe
13	Total Hardness (As CaCO3)	mg/l	200	600	78.000	Safe
14	Turbidity	NTU	1	5	0.500	Safe

- Note:**
- 1)*indicates parameters that are NABL accredited.
 - 2)This test results related to the sample tested above
 - 3)The report shall not to be reproduced in full without approval of authority
 - 4)This is the end of the report


 Authorised signatory
 Mahesh Prasad, (Test Lab Incharge)
 मिशन कैंपस, 30 प्रो, जल।
 सिद्धार्थनगर

Jal Jeevan Mission aims at potable tap water supply to every home
 Let's join hands to ensure drinking water is potable. It helps in preventing water borne diseases and improve public health.


Principal
Siddharth Public School
 Tharauli Road, CMI Lines
 Siddharth Nagar (U.P.)


 प्रबन्धक